



VILLAGE OF MARTIN'S ADDITIONS
7013B Brookville Road ♦ Chevy Chase, Maryland 20815 ♦ 301/656-4112

Ms. Kim Watson,
Vice-President for Maryland Affairs
PEPCO
701 Ninth Street, NW.,
Washington, D.C. 20068

August 23, 2010

Dear Ms. Watson:

On behalf of the Village of Martin's Additions we would like to thank you for working so closely with our Village Manager, Ms. Jean Sperling, during the recent outage problems in our municipality.

The addresses in Martin's Additions that are listed below have experienced consistent long term outages in the winter and summer storms as well as persistent sporadic outages. The addresses are clustered in the north end of Martin's Additions in adjoining blocks. The lack of reliable PEPCO service is a chronic problem.

We are aware that you and Ms. Sperling have discussed these locations in detail as have two representatives from your Reliability Office, Mrs. Brown and Mrs. Mostofi. The purpose of this letter is to seek confirmation that PEPCO will be thoroughly investigating the area defined by these outages. These outages closely align themselves with outages that have been experienced in our neighboring Chevy Chase Section 5. Those outages in Section 5 were described to you in a letter from a resident there, Mr. Charles Larson.

We are encouraged by the plan you have put forth to address the necessary improvements in reliability, including:

- *The need to get more detailed input from key stakeholders* – please consider the list of frequently affected residents to be the key Martin's Additions stakeholders in improvements.
- *Performing more detailed engineering analysis on selected substations and feeders*— please evaluate the feeders and substation that are supplying the section of Martin's Additions under discussion here.
- *Enlisting the support of government officials in gaining support for enacting plans going forward*—you have the support of the Village Council of Martin's Additions and the commitment to work with you to solve these problems as they particularly affect our residents and the community at large. We support the Comprehensive Reliability Plans you identified in your August report. If we can assist in any way to achieve rapid problem identification and solution development please let us know.

Please confirm that you have put our particular power problems on your reliability assessment list. Again we look forward to working with you to solve these problems.

Sincerely,



Richard Krajeck
Chairman




Chris Mueller
Vice-Chairman



Arthur Alexander
Treasurer



Jill Filipczyk
Secretary



Michael E. Zielinski
Council Member

Village of Martin's Additions

7013 B Brookville Road

Chevy Chase, MD 20815

301-656-4112; FAX 301-656-0030

martinsadditions@verizon.net; www.martinsadditions.org.

ADDRESSES AFFECTED BY PERSISTENT OUTAGES IN THE NORTHERN END OF
MARTIN'S ADDITIONS ARE LISTED BELOW:

3503, 3501, 3416, 3413, 3411, 3409, 3408, 3407, 3406, 3404, 3402, 3219 **Thornapple Street**
[East of Brookville Road. These properties are contiguous although the address numbers might suggest otherwise]

7215, 7216, 7218, 7219, 7220, 7223 **Chestnut Street**
[Close to intersection with Thornapple Street]

7200, 7202, 7203, 7206, 7207, 7208, 7209, 7210, 7211, 7213, 7214, 7215, 7216, 7218, 7219, 7220,
7221, 7222, 7223 **Delfield Street**
[Between Taylor Street and Thornapple Street; east of Brookville Road]

7301, 7303, 7306, 7308, 7309, 7310, 7311, 7312, 7313, 7314, 7315, 7316, 7318, 7320 **Delfield Street** [North of Thornapple, east of Brookville Road, referred to as "Dead-end" Delfield]

7200, 7201, 7203, 7204, 7205, 7206, 7207, 7209, 7210, 7211, 7213, 7300, 7301, 7302, 7303,
7304, 7305, 7306, 7307, 7308, 7309, 7311, 7313, 7313, 7317, 7400, 7401, 7404, 7405 **Summit Ave**
[East of Brookville Road, South of Leland Street to intersection with Taylor Street]

3404, 3406, 3408, 3409, 3410, 3411 **Taylor Street**
[Intersects with Summit Ave; outage area runs between Summit and Delfield]

CC: *Mr. Thomas Graham*, President, Pepco Region, 701 Ninth Street, NW, Washington, D.C. 20068
Mrs. W.A. Brown, PEPCO Reliability Office, Senior Customer Reliability Investigator,
PEPCO 3400 Benning Road N.E., Washington, D.C. 20019-1599
Ms. Zenayda Mostofi, PEPCO Reliability Office
Mr. Joseph Rigby, President and CEO, PEPCO, 701 Ninth Street, NW, Washington,
D.C. 20068
Mr. Douglas R. M. Nazarian, Chairman, Maryland Public Service Commission,
45 Calvert Street, Annapolis, MD 21401
Mr. Ike Leggett, Montgomery County Executive, Executive Office Building, 101 Monroe
Street, 2nd Floor, Rockville, MD 20850
Mr. Roger Berliner, Montgomery County Council, 100 Maryland Avenue, Rockville, MD
20850
Mr. Chris Van Hollen, 1707 Longworth House Office Building, Washington D.C. 20515

Village of Martin's Additions
7013 B Brookville Road
Chevy Chase, MD 20815
301-656-4112; FAX 301-656-0030
martinsadditions@verizon.net; www.martinsadditions.org.